



PROJECT PROFILE
Litigation Preparation
Photo Documentation



Using lasers to show out of plumb work



Forensic Damage Consultants LLC was assigned by the Legal team to photo document a upscale remodel that had serious workmanship defects. The Property owner hired a contractor out of the phone book and paid them ahead of each phase. The owner paid exaggerated costs for extremely bad work.

Our mission was to photo document the case for litigation. Here are a few of the many photos taken to depict the conditions in the high value residence. The problems were endless.

